FPM-600 POWER METER



The highly versatile FPM-600 Power Meter is designed for link and system qualification.

KEY FEATURES

High accuracy, wide dynamic range and high power measurement capability (up to 26 dBm)

Memory capacity of 1000 data items; enables data transfer to a PC via USB connection

User-configurable pass/fail thresholds with LED indicator

Over 40 calibrated wavelengths, and hold Min/Max power function

Rechargeable batteries

Error-free, time-saving test features: automatic wavelength switching, no offset nulling

Low cost of ownership: three-year warranty and recommended calibration interval



SUITED FOR ALL NETWORK TYPES

The FPM-600 is a very powerful tool for the most demanding applications such as high-speed DWDM or CWDM network qualification.

With more than 40 calibrated wavelengths, including all CWDM wavelengths, it allows for user-defined measurement wavelengths, using the interpolation method between calibrated points. Use its Hold Min/Max Power function to measure system power burst or fluctuations.

ERROR-FREE, TIME SAVING TEST FEATURES

When used in combination with a FLS-600 Light Source in Auto-Switching mode, the power meter automatically recognizes the wavelength in use and switches to the proper calibration parameter. At the press of a button, you can store results for all wavelengths at once.

FTTx READY

EXFO's FPM-600 allows for the testing of passive optical networks (PONs) at 1310 nm, 1490 nm and 1550 nm, the three wavelengths recommended by the ITU-T (G.983.3) for PONs.at once.

RUGGED AND VERSATILE

Like all EXFO portable instruments, the FPM-600 is built for top ruggedness and versatility, perfect for the harshest test conditions. It features a keypad/LCD backlight, for easy operation in darker environments. What's more, it is powered by a rechargeable battery.

REPORTING SOFTWARE

This new software tool enables you to produce professional-looking reports with comprehensive documentation. It also offers these functionalities:

- > Two test files can be merged into one test report (see note no. 3)
- > Pass/fail thresholds that are active during download are automatically activated and displayed in the Report Viewer
- > One-touch storage of results for all wavelengths at once (see note no. 1)
- > Unit B configuration information can be input and documented (see note no. 2)
- > Data transfer can be launched from the Report Viewer window (see note no. 3)
- > A pass/fail threshold can be set for an individual fiber or wavelength (see note no. 4)





Optical Report Viewer: main window



Delete Copy All	12_20_2004.hl/dk)*	
FasTesT FasTesTFTTx	Power Power Power Manual FasTesT (W) (dBm) (dB) OFL Thresholds	- Open
Job ID: 123 Reason: New installation Contractor: ABC Customer: EXFO Custom job 1:	Dete: 12/2/005 11:23:14 AM Operator A: Paul Operator B: John Custem job 2:	Sarre As
Cable Information Cable ID: CAB1 Location A: Ouebec Cable Mfr.: Corning Low count:	Location B: Montreal Cable Type: SMF-28e High count:	Prec 3 Launch
Unit Name: F	HE A Unit B PAUF 07 5000 S984 <u>XXXXXXX</u>	data transfer and converter/merge

Optical Report Viewer: main window



Delete	Copy All	Edit Job Informat	ion Edit Cable Informat	ion Fastest th	reshold		Circle Circle	
FasTesT				Manual ORL	FasTesT Thresholds	1		
Power (dB	9			Selecti	on: All None	-		18
01101 (u	<i>'</i>					1		
Fiber ID	Wavelength (nm)	Power (dB)	Reference 1 (dBm)	hreshold (dB)	Pass/Fail		Save /	
A	850	1.3	-53.18	-30.00	Pass		C	
<u>0014</u>	Unit A: FPM/FOT-6 < <edit>></edit>	00 № 339884	,			-		<u></u>
A	860	19.23	-53.18	<u>-30.00</u>	Pass	•	Seb	
0015	Unit A: FPM/FOT-6 < <edit>></edit>	00 N≌ 339884	· · · · ·				6	6
Y	850	12.12	-53.18	-30.00	Pass		Prir	nt
0016_	Unit A: FPM/FOT-6 < <edit>></edit>	00 N≌ 339884					Tran	
0017	850	7.9	-53.18	<u>-30.00</u>	Pass			
	Unit A: FPM/FOT-6 < <edit>></edit>	00 N≌ 339684					Convert	_
V	850	5.7	-53.18	<u>-30.00</u>	Pass		0	۲
0018	Unit A: FPM/FOT-6 < <edit>></edit>	00 N≌ 339884					неlp	About
V	850	5.4	-53.18	<u>-30.00</u>	Pass		đ	b
0019	Unit A: FPM/FOT-6	00 N₂ 339884				-	Ex	át
(FO							12/2/2005	11:27 A

Select all or no results in a specific section

Apply a specific threshold to each fiber and/or wavelength and get a complete pass/fail status (not available with FasTesT results)

Optical Report Viewer: main window

SPECIFICATIONS^a

SPELIFICATIONS*			
Model	FPM-602	FPM-602X	
Detector	Ge	GeX	
Power range (dBm) ^b	10 to -70	26 to -55	
Wavelength range (nm)	800 to 1650	800 to 1650	
Calibrated wavelengths (nm)	800, 820, 830, 840, 850, 860, 870, 880, 910, 980, 1270, 1280, 1290, 1300, 1310, 1320, 1330, 1340, 1350, 1370, 1390, 1410, 1430, 1450, 1460, 1470, 1480, 1490, 1500, 1510, 1520, 1530, 1540, 1550, 1560, 1570, 1580, 1590, 1600, 1610, 1620, 1630, 1640, 1650	, ,	
Power uncertainty °	±5 % ± 0.1 nW	±5 % ± 3 nW	
Resolution (dB)	±0.01 (10 dBm to −60 dBm)	±0.01 (26 dBm to -45 dBm)	
Automatic offset nulling ^d	Yes	Yes	
Display units	dB, dBm, W	dB, dBm, W	
Tone detection	270 Hz, 1 kHz and 2 kHz	270 Hz, 1 kHz and 2 kHz	
Auto-switching ^e	Yes	Yes	
Warm-up period (min) ^f	0	0	
Data storage (items)	More than 1000	More than 1000	
Battery life (hours) (typical)	72	72	
Warranty and recommended recalibration interval (years)	3	3	

Notes

a. Guaranteed unless otherwise specified. All specifications valid at 1550 nm and 23 °C \pm 1 °C, with an FC connector.

b. In CW mode; sensitivity defined as 6 x rms noise level.

c. For calibrated wavelengths. Valid up to 20 dBm for FPM-602X.

d. For power > -40 dBm for FPM-602, and > -25 dBm for FPM-602X.

e. ~At ~850~nm, ~1300~nm, ~1310~nm, ~1490~nm, ~1550~nm ~and ~1650~nm; for ~power > -50~dBm ~for FPM-602~and > -40~dBm ~(typical)~for FPM-602X.

f. For a variation of \leq 0.06 dB at power levels \geq -40 dBm for FPM-602 and \geq -25 dBm for FPM-602X.



FXFO

STANDARD ACCESSORIES

User guide, Certificate of Calibration, instrument stickers in six languages, AC adapter/charger, lithium ion battery, shoulder strap, carrying case, USB cable.

GENERAL SPECIFICATIONS		
Size (H x W x D)	190 mm x 100 mm x 55 mm (7 ½ in x 4 in x 2 ½ in)	
Weight (with battery)	0.48 kg (1.1 lb)	
Temperature operating storage	−10 °C to 50 °C (14 °F to 122 °F) −40 °C to 70 °C (−40 °F to 158 °F)	
Relative humidity	0 % to 95 % noncondensing	

LASER SAFETY

IEC 60825-1:2007	
21 CFR 1040.10	
LASER RADIATION	
AVOID DIRECT EYE EXPOSURE CLASS 3B LASER PRODUCT	
λ: 650 ±10 nm	
Pout maximum < 5mW (into free space)	

ORDERING INFORMATION



EXFO Headquarters > Tel.: +1 418 683-0211 | Toll-free: +1 800 663-3936 (USA and Canada) | Fax: +1 418 683-2170 | info@EXFO.com | www.EXFO.com

EXFO serves over 2000 customers in more than 100 countries. To find your local office contact details, please go to www.EXFO.com/contact.

EXFO is certified ISO 9001 and attests to the quality of these products. EXFO has made every effort to ensure that the information contained in this specification sheet is accurate. However, we accept no responsibility for any errors or omissions, and we reserve the right to modify design, characteristics and products at any time without obligation. Units of measurement in this document conform to SI standards and practices. In addition, all of EXFO's manufactured products are compliant with the European Union's WEEE directive. For more information, please visit www.EXFO.com/recycle. Contact EXFO for prices and availability or to obtain the phone number of your local EXFO distributor.

For the most recent version of this spec sheet, please go to the EXFO website at www.EXFO.com/specs.

In case of discrepancy, the Web version takes precedence over any printed literature.

Keep this document for future reference.

